

1

ScanRate is an OUTPUT that runs at 1/2 of the PLC scan rate.

Connect your favorite bit of test equipment to this OUTPUT.

2

ScanRate



ScanRate
01 (OUT)